



503851

Site Name Ren Plastics - S. Cedar, Dawn AveCounty InghamCALL LOG

- 1) Verify Site Location and Size.
- 2) Verify # and size of each containment structure.
- 3) Is there existing exposure of people documented?
- 4) Is the site fenced? Is it secure?
- 5) If sampling was done, how were samples collected? i.e. random selective, surface grab, composite etc..
- 6) Has the fire marshall considered the site a fire hazard?
- 7) What type of companies used the site? (Origin of chemicals)

<u>DATE</u>	<u>AGENCY</u>	<u>PHONE NUMBER</u>	<u>PERSON CONTACTED</u>
12/23/86	Ren Plastics	351-5900	Mike Munsel

- Mike stated that no follow-up sampling was performed after soils were removed.

- The sludge that remained in the bottom of the septic tank at the S. Cedar site was shoveled out + removed.

- Monitoring wells were pulled at both the Dawn Ave + S. Cedar locations

Prepared by: R. H. H. H.